

Xinput Calibrator for Touchscreen Calibration

Get xinput_calibrator

The generic calibration tool xinput_calibrator is a program for calibrating your touchscreen, when using the X Window System.

Install xinput_calibrator:

```
___ sudo apt-get install xinput_calibrator
```

Use calibrate tool

Connect one (if multiple) touch screen and on the command line, run:

```
___ xinput_calibrator
```

The [UI](#) [1] screen will show an x at each point of the screen. Click the x at each red point to create a calibration. Once a valid calibration is created, the tool will prompt you to save the set up to a specific config file.

If multiple monitors are being used, the calibration needs to be mapped correctly.

Tags: [Xinput](#) [2]
[Touchscreen](#) [3]

Source URL: <http://localhost:8888/kb2017/xinput-calibrator-touchscreen-calibration-0>

Links

[1] <http://greenseainc.com/kb/lexicon/1#ui>

[2] <http://localhost:8888/kb2017/tags/xinput>

[3] <http://localhost:8888/kb2017/tags/touchscreen>